

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

## **Restart of Chip Serial Number at Zero**

## Restart of Chip Serial Number at Zero

### ► Products affected:

Sales Name	SP N°	OPN	Package
TDA5225	SP000507672	TDA5225XUMA1	PG-TSSOP-28-17
TDA5225HT	SP000857470	TDA5225HTXUMA1	PG-TSSOP-28-17
TDA5235	SP000507674	TDA5235XUMA1	PG-TSSOP-28-17
TDA5235HT	SP001098782	TDA5235HTXUMA1	PG-TSSOP-28-17
TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28-17

### ► Detailed Change Information:

**Subject:** Unique 32-bit serial number will restart at zero. Please refer to  
 TDA5240 Datasheet 2.5.6  
 TDA5235 Datasheet 2.5.6  
 TDA5225 Datasheet 2.5.5  
 TDA5235HT Datasheet 1.2  
 TDA5225HT Datasheet 1.2

**Reason:** Maximum number of chip serial number is close to completion.

Description:	<u>Old</u>	<u>New</u>
Chip Serial Number:	<ul style="list-style-type: none"> <li>Unique 32-bit serial number</li> </ul>	<ul style="list-style-type: none"> <li>Restarting of chip serial number sequence.</li> </ul>

### ► Product Identification:

Traceability is ensured via lot number and date code.

### ► Impact of Change:

Not applicable (neither change of product nor process).

### ► Attachments:

N.A.

### ► Intended start of delivery:

From April 2018 onwards.