

Product Change Notice

PCN#: EE-PCN17032

06/15/2017

CLASSIFICATION OF CHANGE:

Assembly site.

DESCRIPTION OF CHANGE:

Eaton is adding an additional manufacturing location for selected power inductors. A marking code of CG is in the date code to identify the manufacturing plant.

REASON FOR CHANGE:

The additional manufacturing location site will enhance our ability and capacity to provide better services to our customers.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

It is running change, no effect on the quality, reliability, or performance. This change does not impact to fit – form – function.

PARTS FAMILIES AFFECTED:

FP3-R
LD1-R
LD2-R

Specific part numbers are listed on the following page.

TIME SCHEDULE:

Start Shipment Date: Sep 2017. Existing inventory should be to be used as is.

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Steve Subiry, Global Product Manager –Magnetics

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

PARTS NUMBERS AFFECTED:

FP3-R10-R	FP3-R47-R	FP3-1R0-R	FP3-2R0-R	FP3-4R7-R
FP3-R20-R	FP3-R68-R	FP3-1R5-R	FP3-3R3-R	FP3-8R2-R
FP3-100-R	FP3-150-R			
LD1-1R0-R	LD1-3R3-R	LD1-8R2-R	LD1-220-R	LD1-560-R
LD1-1R4-R	LD1-3R9-R	LD1-100-R	LD1-270-R	LD1-680-R
LD1-1R8-R	LD1-4R7-R	LD1-120-R	LD1-330-R	LD1-820-R
LD1-2R2-R	LD1-5R6-R	LD1-150-R	LD1-390-R	LD1-101-R
LD1-2R7-R	LD1-6R8-R	LD1-180-R	LD1-470-R	LD1-151-R
LD1-221-R	LD1-331-R			
LD2-100-R	LD2-220-R	LD2-470-R	LD2-101-R	LD2-221-R
LD2-120-R	LD2-270-R	LD2-560-R	LD2-121-R	LD2-271-R
LD2-150-R	LD2-330-R	LD2-680-R	LD2-151-R	LD2-331-R
LD2-180-R	LD2-390-R	LD2-820-R	LD2-181-R	LD2-391-R
LD2-471-R				