



Product Change Notification / MFOL-24SJQF382

Date:

31-May-2022

Product Category:

Bluetooth Module, Wireless Modules

PCN Type:

End of Life

Notification Subject:

eSign# E000104918: End of Life (EOL) of RN42xx and RN52xx device families.

Affected CPNs:

[MFOL-24SJQF382_Affected_CPN_05312022.pdf](#)

[MFOL-24SJQF382_Affected_CPN_05312022.csv](#)

Notification Text:

PCN Status:End of Life (EOL) Notification

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The RN42xx and RN52xx device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after the date listed in the attached PCN_#_Suggested_Replacements file. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates: Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): Please refer to PCN_#_Suggested_Replacements (excel file) for the list of LTB dates identified per catalog part number.

Last date for shipments (LTS): Please refer to PCN_#_Suggested_Replacements (excel file) for the list of LTS dates identified per catalog part number.

Revision History: **April 27, 2022:** Issued EOL notification.

May 31, 2022: Re-issued EOL notice. Updated the affected CPN, notification subject, EOL description to remove RN-41xx, RN-24xx, and RN-27xx device families.

Attachments:

[PCN_MFOL-24SJQF382_Suggested_Replacements.xlsx](#)

[PCN_MFOL-24SJQF382_Suggested_Replacements.pdf](#)

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

RN42NAPL-I/RM545

RN42NHCI-I/RM

RN52CVC-I/RM116

RN42NHID-I/RM

RN52SRC-I/RM100

RN42-I/RMCOS477

RN52UDF-I/RM116

RN52APC-I/RM117

RN42N-I/RMCOS477

RN42NU-I/RM

RN42NAPL-I/RM

RN42-I/RMEVO519

RN42-I/RMMGK477

RN52-I/RM110

RN42-I/RMETI540