

Harwin plc Fitzherbert Road Farlington, Portsmouth Hampshire PO6 1RT United Kingdom

Reception: +44 (0)23 9231 4545 Sales Desk: +44 (0)23 9237 0451

Monday 5th March, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete. These items have a **Last Time Buy date of 7<sup>th</sup> September 2018** (approximately 6 months):

- M80-080 Datamate Friction Latch
- B5743-1xx-M-T-R, B5743-2xx-M-T-R
- M80-667 series
- M80-748 series
- M80-763 series
- M80-781 series
- M80-804 series
- M80-805 series
- M80-814 series
- M80-815 series

- M80-816 series
- M80-817 series
- M80-827, M80-827P series
- M80-835 series
- M80-839 series
- M80-846 series
- M80-863 series
- M80-881 series
- M80-883 series
- Customer Special items with friction latches

Please see the following spreadsheet for a detailed list of affected items: <a href="https://cdn.harwin.com/pdfs/Obsolescence">https://cdn.harwin.com/pdfs/Obsolescence</a> notification spreadsheet Harwin Friction Latch Datamate <a href="https://cdn.harwin.com/pdfs/Obsolescence">O5 March 2018.xlsx</a>

These items cover all Datamate L-Tek products that use the Friction Latch. Unfortunately, we are no longer able to support these product lines. In most cases, we recommend substitution for the unlatched equivalent L-Tek, although there is also the locking latch version available. Please see the attached spreadsheet for the recommended alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team technical@harwin.com