

End of Life Notification EOL20.034

40km & 80km DWDM SFP+ FTLX3671 and FTLX3871 variants

This document is an End of Life Notification (EOL) for II-VI's variant 10G DWDM SFP+ transceivers.

Affected Part Numbers and Recommended Replacement Part Numbers

The II-VI part numbers affected by this EOL notice are as follows:

II-VI EOL Part Number	Suggested Replacement
FTLX3671DTCxx	FTLX3971DTCxx or FTLX6673MTC (Tunable)
FTLX3671DTCxx-xx	FTLX3971DTCxx or FTLX6673MTC (Tunable)
FTLX3671MTCxx	FTLX3971MTCxx
FTLX3671MTCxx-xx	FTLX3971MTCxx-xx
FTLX3871MCCxx	None
FTLX3871MCCxx-xx	None
FTLX3871DCCxx	FTLX6873MCC (Tunable)
FTLX3871DCCxx-xx	FTLX6873MCC (Tunable)

Reason for Discontinuation

The market demand of this legacy product has fallen below sustainable levels. This has resulted in increasing costs and high risk of availability of key components.

End of Life Dates

All last time buy purchase orders must be received by **June 30th 2021**. The last time shipment date will be **September 30th 2021**, or earlier.

Order Acceptance/Change Conditions

Any orders for the discontinued products listed above with a requested ship date after **June 30th 2021** will be non-cancelable and non-returnable (NCNR). The words "non-cancelable, non-returnable" must be clearly indicated on these orders. These orders cannot be changed, rescheduled, or cancelled.

RMA Replacements

After **June 30th 2021**, II-VI reserves the right to replace any of the discontinued products listed above returned under RMA (Return Material Authorization) with either the suggested replacement part or with a credit, at II-VI's discretion.



We apologize in advance for any inconvenience this may cause. Please do not hesitate to call on your local distributor, rep, or local II-VI sales manager for any additional information you need.

For More Information please contact your local II-VI representative, or

II-VI Incorporated 375 Saxonburg Boulevard Saxonburg, PA 16056 photonics.sales@ii-vi.com www.ii-vi.com