


Product/Process Change Notifications



PCN - 15 057

Release Date: July 03 2015

Product Name:	Power Blade		
	Power Blade Vertical Receptacle		
Product Manager:	Daisy Liu		
Subject:	Packaging Change		
Distribution:	General		
Type of Change:	Packaging Change		
Change Description:	<p>Redesign the packaging tray for listed part numbers and change the connector orientation in tray from "tails toward up" to "tails toward side". No change of SPQ and MOQ.</p> <div style="text-align: center;">  </div>		
Reason for Change:	<p>1) Existing "tails toward up" tray has potential damage to the tail of the connector when the package suffers serious shock/vibration during transportation. Optimized new packing with orientation change of the product will avoid the potential damage to the tail.</p> <p>2) FCI has two kinds of packing for PwrBlade V/T REC, the old part numbers created before 2008 are using the packing methods with potential risk due to "tail toward up", while the part numbers created after 2008 are using the new packing with "tail toward side".</p> <p>So this PCN is to change the part numbers packing method for the part numbers created before year 2008.</p>		
Affected Parts:	See attached file		
Effective Date of Change:	October 5, 2015		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	No		
Qual/Test Data Attached?	Yes		
Samples Availability Date:	July	3	2015
Available Alternatives?	N/A		
Questions?	<i>Contact your local FCI Representative, or Product Manager</i>		
	<i>Daisy Liu/Product Manager</i>		
	<i>+86 769 88669320/ Daisy.Liu@fci.com</i>		

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date. PCN is considered approved by the customer if no communication is received within 3 weeks