

August 8<sup>th</sup>, 2022

## Product End of life Notification

Due to rapid changes in technology and, in an effort to optimize our product range, we have decided to stop manufacturing the below products, the tool are now at the end of their life, forcing the cost to increase. In addition, finding suitable parts from reputable suppliers has become increasingly problematic and risk adverse. This is not a good recipe for bringing to you the high quality products and services that you have come to expect from Radiall

Therefore, Radiall announces the obsolescence of the following part number:

INSULATED BANANA PLUGS		
R921390000	R941330000	R941340000
R921391000	R941331000	R941341000
R921392000	R941332000	R941342000
R921393000	R941333000	R941343000
R921394000	R941334000	R941344000
R921396000	R941336000	R941346000

As a result, Radiall will allow a last-time buy on these products based on the guidelines below:

- Radiall sales representative or authorized distributors will be contacting you to determine interest in making a last-time buy. This will be done up to the 31<sup>st</sup> of October 2022, Purchase Orders should be placed within this time frame for delivery accepted till the 31<sup>st</sup> of December 2022.
- All orders placed will be non-cancellable, non-returnable.
- If a quality problem occurs, Radiall leaves the possibility of replacing the defective product within the tool capacity which is at the end of its life. Since the tools will no longer exist, we will not be able to replace any defective parts, and that in this case the only recourse would be a credit note, if the product is recognized as defective by our quality department.

Please do not hesitate to contact your local sales representative or authorized distributors if you have any questions about obsolescence and stock.

Sincerely,

Sylvain Gahery  
RF Product Manager