Product Obsolescence Memo

INDUCTIVE COMPONENTS

Bourns Manufacturers Representatives Corporate Distributor Product Managers Americas Sales Team Asia Sales Team Europe Sales Team Bourns Internal Bourns Plant Managers



May, 2011

MG, MH, MT and MZ Chip Beads Series with Certain Values to be Discontinued

Effective **December 1, 2011**, Bourns will no longer accept orders for certain values of MG, MH, MZ and all values of MT Chip Beads Series. A last time buy is available on or before **November 30, 2011**. A low sales volume and few active customers for these chip bead values necessitates this action. In addition, Bourns will no longer offer samples of the values to be discontinued.

We are not aware of any replacement part for these discontinued chip beads.

Affected part numbers:

MG1608-202Y	MH3225-151Y	MT1608-050Y	MT3225-310Y	MT3266-600Y	MZ1608-152Y
MG1608-222Y	MH3225-201Y	MT1608-090Y	MT3225-520Y	MT4516-101Y	MZ1608-202Y
	MH3225-300Y	MT1608-300Y	MT3225-600Y	MT4516-151Y	MZ2029-152Y
	MH3225-520Y	MT2029-070Y	MT3261-190Y	MT4516-800Y	MZ2029-202Y
	MH3225-650Y	MT2029-100Y	MT3261-260Y	MT4532-121Y	MZ3261-122Y
	MH3225-900Y	MT2029-110Y	MT3261-310Y	MT4532-131Y	MZ3261-202Y
		MT2029-170Y	MT3261-420Y	MT4532-250Y	
		MT2029-260Y	MT3261-500Y	MT4532-700Y	
		MT2029-300Y	MT3261-700Y		
		MT2029-400Y	MT3261-900Y		

If you have any questions, please contact Bourns Customer Service.