

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138

Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)								
PDN #:	N-10-01	Last Buy Da	te:	7/10/2010				
Issue Date:	2/23/2010	Last Ship Da		7/10/2012				
	Rodney Corpuz QA							
	408) 284-8261							
Fax #: (4	408) 284-8591							
E-mail:	Rodney.Corpuz@idt.com							
PRODUCT(S)	AFFECTED: nt Part #(s), if any)	ATTACHM	ENT Yes	□ No				
accept a fab shuto Freescal these de Freescal Returnal	Sendai, Japan. Freescale has inform ny wafer orders after July 24, 2010 down circumstances are beyond th e Sendai wafer fab shut down. Du vices to place device LTB orders f e fab in Sendai, replacement parts oble (NCNR). Any customer date co ontact IDT for further details on d	0 for the devices that are listed the control of IDT. We deeply the to these unforeseen circum for the affected parts by July to cannot be made available. A ode requirements for parts sh	ed in this PDN. The regret the inconveni stances, IDT is requ 10th 2010. Due to th All orders are Non Ca ipped after July 10,	Freescale 150 mm Sendai ience caused by the esting all customers of ne unique process of the ancellable and Non 2011 must be waived.				
<ul> <li>□ Replace slov</li> <li>■ Obsolete Fai</li> <li>□ Obsolete As</li> </ul>	R DISCONTINUANCE: wer speed with faster speed offerin b Technology / Process sembly Technology / Process ckage / Material arket	ngs 🗖 Other:	Freescale 150MM S	Sendai Fab Closure				
As a result of c through this Pr converting to e	<b>NOTIFICATION:</b> discontinuance reason(s) listed aboreduct Discontinuance Notice (PD equivalent devices offered. Please any questions, please feel free a	N). We recommend you to c use acknowledgement below	heck detailed specifi v or E-Mail to reque	ications before st additional information.				
	iny questions, pieuse jeel jree	•		es representative.				
Customer:		E-Mail Addres						
Name/Date:		Phone	e#:					
Title:		Fax	x# :					
CUSTOMER	COMMENTS:							
IDT ACKNO	WLEDGEMENT:							
Received By:		Date:						



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

# **PRODUCT DISCONTINUANCE NOTICE (PDN)**

### Attachment: PDN # N-10-01

Affected Parts	Minimum Order		
Affected Faits	(MOQ)		
MC68150FN33	250		
MC68150FN33R2	250		
MC68150FN40	250		
MC88915EI55	550		
MC88915EI55R2	550		
MC88915EI70	550		
MC88915EI70R2	550		
MC88915FN55	550		
MC88915FN55R2	550		
MC88915FN70	550		
MC88915FN70R2	550		
MC88915TEI100	600		
MC88915TEI100R2	600		
MC88915TEI133	1200		
MC88915TEI133R2	1200		
MC88915TEI160	1200		
MC88915TEI55	600		
MC88915TEI55R2	600		
MC88915TEI70	600		
MC88915TFN100	600		
MC88915TFN100R2	600		
MC88915TFN133	600		
MC88915TFN133R2	600		
MC88915TFN55	600		
MC88915TFN55R2	600		
MC88915TFN70	600		
MC88915TFN70R2	600		
MC88916DW70	600		
MC88916DW80	600		
MC88916EG70	600		
MC88916EG80	600		
MC88920DW	600		
MC88920EG	600		
MC88LV915TEI	1200		
MC88LV915TEIR2	1200		
MC88LV915TFN	1200		
MC88LV915TFNR2	1200		
MC88LV926DW	1200		
MC88LV926DWR2	1200		
MC88LV926EG	1200		
MC88LV926EGR2	1200		



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

# **PRODUCT DISCONTINUANCE NOTICE (PDN)**

Attachment: PDN # N-10-01

		FREE	SCALE				
Freescale Semiconductor, Inc.							
	PI	RODUCT DISCON	TINUANCE UPDA her Copy	ТЕ			
ISSUE DATE:	27-Jan	-2010					
ATTN:	INTEC	INTEG DEVICE TECHNOLOGY					
NOTIFICATION	13644.	13644A					
TITLE:	DISCO	FREESCALE 150MM SENDAI FAB CLOSURE-GENERAL PRODUCT DISCONTINUANCE					
LAST BUY DATH	24-Jul	24-Jul-2010					
LAST SHIP DAT	E: 24-Jul-	2011					
CUSTOMER(S) NTEG DEVICE TE ICSPA) A 20. BOX 67071 ACCOUNTS PAYA COTTS VALLEY ( 5066 USA	BLE	ΞY					
DEVICE(S)							
<u>DEVICE(S)</u> CPN	MPN	Replacement MPN	Replacement Type	Replacement Reason			
CPN J0DD881951J90X	SC9J90X						
CPN J0DD881951J90X J0DD889151J90X	SC9J90X SC5J90X						
CPN J0DD881951J90X	SC9J90X SC5J90X SC2K00S						



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

## **PRODUCT DISCONTINUANCE NOTICE (PDN)**

Attachment: PDN # N-10-01

This notice IS Freescale Confidential Proprietary and is only intended for the customer listed on this notification.

### DESCRIPTION OF CHANGE

Freescale Semiconductor is announcing the discontinuance of the device listed above. All orders for the discontinued product must be received by the last buy date. After the last buy date, no accepted order may be cancelled or changed and no returns of delivered products will be accepted. . This Product Discontinuance is the final notice for customer to place an order for the discontinued product. Derivative devices of a discontinued product family will have the same Last Buy Date and Last Ship Date as this Product Discontinuance even if the derivative is first produced after the date of this Product Discontinuance notice. Products requiring failure analysis, additional testing or other service after the last ship may be subject to additional fees and availability of equipment, materials, or other hardware and software.

### REASON FOR CHANGE

In order to improve our manufacturing efficiency, we have made the decision to refocus our manufacturing on 200mm and 300mm technology and to ramp down 150mm manufacturing, resulting in the closure of the Sendai Fab.

#### ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

Product is being discontinued. Please contact your sales representative for potential replacement parts.

Freescale will consider specific conditions of acceptance of this change submitted within 30 days of receipt of this notice on a case by case basis. To request further data or inquire about samples, please enter a Service Request.

ATTACHMENT(S): N/A