



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000857

DATE: 20-Jun-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS2501S-UNW-111B/T&R	DS2502S+T&R	20-Jun-2018	20-Dec-2018	Part is leaded. Request information on lead-free version
Discontinuance	73S1210F-EB-LITE	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S1210F-EB-LITEMS	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S1215F-EB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8009C-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8009CN-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8009R-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8010C-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8014R-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8014RN-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8023C-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8024C-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	73S8024RN-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	78Q2120C09-DB	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	DS1083LR-U+	N/A	20-Jun-2019	20-Dec-2019	Part can no longer be manufactured
Discontinuance	DS1922S-F5#	N/A	20-Jun-2017	20-Jun-2017	Part can no longer be manufactured
Discontinuance	DS4510U-10+T&R	DS4510U-15+T&R	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX20010DATPK/V+	N/A	20-Jun-2017	20-Jun-2017	The part was not released
Discontinuance	MAX20053AUD/V+G2Z	N/A	20-Jun-2018	20-Dec-2018	The part was not released
Discontinuance	MAX24013E/D+	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX310MJE	N/A	20-Jun-2017	20-Jun-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX31785ETL+T	MAX31785AETL+T	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX4090EUT+T	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX44005EDT+	MAX44009EDT+	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX44005EVKIT+	MAX44009EVKIT#	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MAX44005EVSYS#	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jul-2017

Discontinuance	MAX44205ATC+	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX98371EWW+	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAX98371EWW+T	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	MAXQ612X-2552+	N/A	20-Jun-2017	20-Jun-2017	Part can no longer be manufactured
Discontinuance	MAXWSNENV#	MAX32630FTHR#	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported
Discontinuance	MXB7843EEE+	N/A	20-Jun-2018	20-Dec-2018	Part can no longer be manufactured
Discontinuance	STM1E-SFP-EVK	N/A	20-Jun-2017	20-Jun-2017	EVKIT is No Longer Supported