

#### 1 Products affected

Product hierarchy no. *			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBL	PG	PUG	Туре				
80	084	002	0000006516	See list below	800840020000006516	FMBB NEO	
80	084	002	0000006525	See list below	800840020000006525	FMBB EP	
80	084	002	0000006148	See list below	800840020000006148	FSS	

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


List of part numbers affected							
5500.2605.01	5500.2605.04	5500.2605.07	5500.2611.01	5500.2611.04			
5500.2611.07	5500.2621.01	5500.2621.04	5500.2621.07				
3-123-524	3-123-533	3-123-542					
5500.2053	5500.2054	5500.2055					

## 2 Type of change

Changed ground terminal position

## 3 Detailed description of change

Modification of the product appearance, ground faston terminal moved



# 4 Reason of change

- · Reorganization of production process
- Improved performance

#### 5 Release date

The change will be rolled-out starting wk 33/2021 and lasts approx. 6 months depending on the variant.

Product Change Notification						PCN FMBB and FSS case 48 redesign		
owner	creation date	release date	released by	change order no	rev	page	D40 057 000	
doriaan	12.05.2021	12.05.2021	blumhe	2021809	В	1 of 2	D10-057-322	



# ELECTRONIC COMPONENTS

### 6 Impact of change and recommended action

Form Yes Note new ground terminal position

Fit No No change for dimension Function No No change in function

Manufacturing No No change of production site

Label No No change on label Packaging No No change in packaging

### 7 Reference Documents / Attachments

Kind of document	Remarks
FMBB NEO data sheet	
FMBB EP data sheet	
FSS data sheet	

Product Change Notification						PCN FMBB and FSS case 48 redesign		
owner	creation date	release date	released by	change order no	rev	page	D10-057-322	
doriaan	12.05.2021	12.05.2021	blumhe	2021809	В	2 of 2		