

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Software

### **Product Affected**

Part Number	Description	Old Revision	New Revision
XPD1001000-01	XPORT DIRECT PLUS DEVICE NETWORKING MODULE, BULK, ROHS	E13	F13
XPD100100K-01	XPORT DIRECT PLUS DEVICE NETWORKING MODULE, KIT, ROHS	C13	D13
XPD100100S-01	XPORT DIRECT PLUS DEVICE NETWORKING MODULE, SAMPLE, ROHS	E14	F14
XPDNC2000-01	XPORT DIRECT PLUS DEVICE NETWORKING MODULE, NO RJ45 JACK, BULK, RoHS	D13	E13
XPDNC200S-01	XPORT DIRECT PLUS DEVICE NETWORKING MODULE, NO RJ45 JACK, SAMPLE, RoHS	D14	E14

### **Description and Extent of Change**

Lantronix is pleased to announce the release of Application Firmware version 7.0.0.3 and Web Manager version 2.0.0.13.

BUG FIXES:

- Change baudrate of Channel 1 on the fly via Telnet
- Cobos: update copyright information to 2021
- By default SNMP need to disabled across all cobos products

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <http://www.lantronix.com/support/downloads>.

### **Effect of Change on Fit, Form, or Function**

Functional changes as noted above.

### **Effective Date of Change**

This change will go into effect for the listed products built from **April 11, 2022** onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.