



Product Change Notification

TE Connectivity

Product Change Notification: P-16-013592

PCN Date: 22-SEP-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Change PCF relay case marking from ink marking to laser marking

Description of Changes

As part of our ongoing efforts to pursuit more greener products, TE decided to change PCF relay case marking from ink marking to laser marking. Will switch to laser marking from week1640 gradually. The actual switch time of every relay type will depend on the actual order status. The new laser marking will keep the same marking content completely and no impact on relay function and identification

Ink marking and laser marking



Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):

26-SEP-2016

Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1461477-4	NO			"PCF-112D1M-2,000"			
1461477-4	NO			"PCF-112D1M-2,000"			
1721929-1	NO			"PCFN-112H2MG,000"			
1721929-1	NO			"PCFN-112H2MG,000"			
2071169-1	NO			"PCFN-112H2MS,02000"			
2071169-1	NO			"PCFN-112H2MS,02000"			
2071169-2	NO			"PCFN-124H2MS,02000"			
2071169-2	NO			"PCFN-124H2MS,02000"			
3-1419153-4	NO			"PCF-112D2M,000"			
3-1419153-4	NO			"PCF-112D2M,000"			
3-1419153-5	NO			"PCFN-112D2M,000"			
3-1419153-5	NO			"PCFN-112D2M,000"			
5-1440002-8	NO			"PCF-124D2M,000"			
5-1440002-8	NO			"PCF-124D2M,000"			
9-1419129-2	NO			"PCF-112D1M,000", "PCF-112D1M.000"			
9-1419129-2	NO			"PCF-112D1M,000", "PCF-112D1M.000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1721929-1	NO			"PCFN-112H2MG,000"			
2071169-1	NO			"PCFN-112H2MS,02000"			
2071169-2	NO			"PCFN-124H2MS,02000"			
3-1419153-4	NO			"PCF-112D2M,000"			
3-1419153-8	NO			"PCFN-112D2M,000"			
5-1440002-8	NO			"PCF-124D2M,000"			
9-1419129-2	NO			"PCF-112D1M,000", "PCF-112D1M.000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1721929-1	NO			"PCFN-112H2MG,000"			
2071169-1	NO			"PCFN-112H2MS,02000"			
2071169-2	NO			"PCFN-124H2MS,02000"			
3-1419153-4	NO			"PCF-112D2M,000"			
3-1419153-8	NO			"PCFN-112D2M,000"			
5-1440002-8	NO			"PCF-124D2M,000"			
9-1419129-2	NO			"PCF-112D1M,000", "PCF-112D1M.000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1461477-4	NO			"PCF-112D1M-2,000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1461477-4	NO			"PCF-112D1M-2,000"			