

Product Discontinuation

PDN-PCC-755-2017

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
PCC - PCB Connectors	AAC	Product Discontinuation	Notify Distributors and Field	8/4/2017

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Dear Sir or Madam

It is always our goal to offer you state-of-the-art, and up-to-date products for your application. For this reason, it may be necessary from time to time, for economical or technical reasons, to remove one of our components from our product range.

We herewith discontinue the part families PT 2,5/..-PVH-5,0, PST 1,3/..-LH-5,0 and PST 1,3/..-LV-5,0. Part numbers currently sold in the U.S. are included on this document. You will find a complete list of all affected part numbers, and potential replacement part numbers in the attachment.

We thank you for your understanding.

Stock Status

Can existing stock still be used?

Is mixture of stock acceptable?

Transaction Dates

Last Buy from Phoenix Contact: 10/30/2017

Last Scheduled Ship from Phoenix Contact: 4/30/2018



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Harold McKee
hmckee@phoenixcon.com

Thank you,

James Dunbar

Product Marketing Manager PCC



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
1704165	PT 2,5/ 2-PVH-5,0		
1704178	PT 2,5/ 3-PVH-5,0		
1704181	PT 2,5/ 4-PVH-5,0		
1799675	PT 2,5/ 4-PVH-5,0 BD:12-9 SO		
1704194	PT 2,5/ 5-PVH-5,0		
1704204	PT 2,5/ 6-PVH-5,0		
1704217	PT 2,5/ 7-PVH-5,0		
1704220	PT 2,5/ 8-PVH-5,0		
1704233	PT 2,5/ 9-PVH-5,0		
1704246	PT 2,5/10-PVH-5,0		
1704259	PT 2,5/11-PVH-5,0		
1704262	PT 2,5/12-PVH-5,0		
1704275	PST 1,3/ 2-LH-5,0		
1704291	PST 1,3/ 3-LH-5,0		
1704327	PST 1,3/ 4-LH-5,0		
1704356	PST 1,3/ 5-LH-5,0		
1704369	PST 1,3/ 6-LH-5,0		
1704372	PST 1,3/ 7-LH-5,0		
1704385	PST 1,3/ 8-LH-5,0		
1704398	PST 1,3/ 9-LH-5,0		
1704408	PST 1,3/10-LH-5,0		
1704411	PST 1,3/11-LH-5,0		
1704424	PST 1,3/12-LH-5,0		
1704437	PST 1,3/ 2-LV-5,0		
1704453	PST 1,3/ 3-LV-5,0		
1704482	PST 1,3/ 4-LV-5,0		
1703057	PST 1,3/ 4-LV-5,0 L18		
1704518	PST 1,3/ 5-LV-5,0		
1707682	PST 1,3/ 5-LV-5,0 L18		
1704521	PST 1,3/ 6-LV-5,0		
1704534	PST 1,3/ 7-LV-5,0		
1704547	PST 1,3/ 8-LV-5,0		
1704550	PST 1,3/ 9-LV-5,0		
1704563	PST 1,3/10-LV-5,0		
1704576	PST 1,3/11-LV-5,0		
1704589	PST 1,3/12-LV-5,0		