

User Registration

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, “how-to” and design documents, product change notices (PCN) and other valuable content available only to registered users. <http://www.silabs.com/profile>

Bulletin Date: 4/1/2015		Bulletin Effective Date: 4/1/2015	
Title: EFM8UB20 Revision 1.2 Data Sheet Update			
Originator: Kafai Leung		Phone: +65 6511-7750	Dept: MCU Marketing
Customer Contact: Kathy Haggar		Phone: +1 512-532-5261	Dept: Sales
Bulletin Details			
Description: In Table 4.3, Reset and Supply Monitor, of the EFM8UB2 revision 1.2 data sheet, the Max Accuracy columns have been updated to indicate 1 ms VDD Ramp Time.			
Reason: Silicon Labs is issuing this change notification to the EFM8UB2 data sheet in order to correct a typographical error regarding the VDD Ramp Time listed in Table 4.3 Reset and Supply Monitor of the data sheet.			
Product Identification: EFM8UB20F64G-A-QFP48 EFM8UB20F64G-A-QFP32 EFM8UB20F64G-A-QFN32 EFM8UB20F32G-A-QFP48 EFM8UB20F32G-A-QFP32 EFM8UB20F32G-A-QFN32			
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy. Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at www.silabs.com			
Customer Actions Needed: Review data sheet 1.2			