

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

PDN #: M000818

DATE: 12-Feb-2016

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS1088CX-133+	N/A			Part reactivated from prior notice: M000816
Reactivation	DS1088CX-133+T	N/A			Part reactivated from prior notice: M000816
Reactivation	DS1339C-2#	DS1339C-3#			Part reactivated from prior notice: M000817
Reactivation	DS1339C-3#	DS1339C-2#			Part reactivated from prior notice: M000817
Reactivation	MAX2180AEVKIT#	N/A			Part reactivated from prior notice: M000790
Lead-Free Conversion	DS1856B-020	DS1856B-020+	13-Aug-2016	11-Feb-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS1859E-020	DS1859E-020+	13-Aug-2016	11-Feb-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	PHY1097-02DS-FR	N/A	13-Aug-2016	11-Feb-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	PHY1097-02DS-WR	N/A	13-Aug-2016	11-Feb-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS12885TN+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	DS2740EVKIT+	DS2756EVKIT+	12-Feb-2016	12-Feb-2016	EVKIT is No Longer Supported
Discontinuance	DS8313-RRX+	DS8005-RRX+	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	DSCIGM1-CC3+T&R	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0400C778BF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0400C781SF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0400C782SF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0400K778BF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0400K782SF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	IC0410C778BF+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX1427ETN+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX14522AEWC+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX14522AEZC+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX14811CTN+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX1504ZETL+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX1543ETP+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX17141ETG+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Mar-2016

Discontinuance	MAX1716EEG	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX17205EVKIT#	MAX17205GEVKIT#	12-Feb-2016	12-Feb-2016	EVKIT is No Longer Supported
Discontinuance	MAX232ACPE+WCC1	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX232ACSE+TWCC1	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX232ACWE+TWCC1	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX2990EVKITB#	MAX2990EVKITBC#	12-Feb-2016	12-Feb-2016	EVKIT is No Longer Supported
Discontinuance	MAX2990EVKITC#	MAX2990EVKITBC#	12-Feb-2016	12-Feb-2016	EVKIT is No Longer Supported
Discontinuance	MAX3246EEBX	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX32550-LNJ+W	MAX32550-LNJ+	13-Aug-2016	11-Feb-2018	The part was not released
Discontinuance	MAX32550-LNS+W	MAX32550-LNS+	13-Aug-2016	11-Feb-2018	The part was not released
Discontinuance	MAX32590-LNS+W	MAX32590-LNS+	13-Aug-2016	11-Feb-2018	The part was not released
Discontinuance	MAX34440ETL+	MAX34440ETLA1+	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX34440ETL+T	MAX34440ETLA1+T	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX34463AA00+	MAX34463EXQA1+	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX34463AA00+T	MAX34463EXQA1+T	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX35101EVKIT#	N/A	12-Feb-2016	12-Feb-2016	EVKIT is No Longer Supported
Discontinuance	MAX3723UTP+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX3723UTP+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX3784AUTE+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX3784AUTE+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX3784UTE+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX4399CTK+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX4760AEWX+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX4803ETN+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX5950ETJ+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX5951ETJ+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX5963UTL+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX614ESA	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX6946CAWE+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX767SCAP	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX77179EWC+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8629ETI+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8645XETI+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8645XETI+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8683ETM+TCH1	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8736BGTL+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Mar-2016

Discontinuance	MAX8736ETL+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8739ETP+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8759ETI+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8786GTL+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8798AETX+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX88000EDT+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8844YETD+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8844YETD+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8844ZETD+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8844ZETD+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX8916ITL+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9515ABS+G45	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9515ABS+TG45	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9539EUI+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9552EUD+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9595CTM+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9673ETI+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9673ETI+T	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAX9673ETI+TG0E	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	MAXQ3100-EMN+	N/A	13-Aug-2016	11-Feb-2018	Part can no longer be manufactured
Discontinuance	SC1869A-00B00E	SC1894A-00C13E	13-Aug-2016	11-Feb-2018	The part was not released